

General Information

New planned legislation
valid from November 2017

NEW LEGISLATION
flashing direction
indicator by
side marker
lamps

Side marker lamps shall flash in turn

This regulation is based on the coming update of ECE 48 to Rev. 6

Important revision in the ECE 48.



The new revision provides for that all side markers must flash in simultaneously with the direction indicator from the rear lamp, or you must mounted three CAT 5 direction indicators on each side.

The new revision (Series 06 supplement 6) in the ECE 48 is mandatory for vehicle O3 and O4 homologated after 18th of November 2017 and possible from 1st of October 2015.

For retrofitting must be ensured that the Rev. 6 fulfilled.

The exact text of the law is on our homepage ready to download. www.aspoeck.com

For this change the company Aspöck developed two different possibilities.

SOLUTION 1

A separate harness which includes a control gear, we call them "SMCG"



PART NO:	
SMCG right	75-0328-001
SMCG left	75-0329-001
SMCG right + left	75-0331-001

SOLUTION 2

A unit which looks like an relay. The „SMCG relay“ gives you the opportunity to fit them into the Aspöck junction boxes or rear lamps (Europoint III, Europoint II, Ecopoint II)



PART NO:	
SMCG relay	12-3970-584

Both SMCG units are very simple to add into an actual Aspöck lightning system.